


GROUT INJECTION SPECIALISTS



JOB DESCRIPTION
Ground collapse
28 Holland Road, Spalding

JOB No: 5737

DATE: 8th Oct 2007



Excavated face showing fullness of lenses and fissures in order to arrest settlement in marginal soils.

Tam Pur 110 & Tam Acryl 2000 injections